

problem: continuity G2 and follow curve of the hol

Послан Ilestе - 17.12.2011 18:30

I need help :(, I have two simple surfaces, but I can't achieve G2 continuity and follow the curve of the hole for the headlight. You can download file from www.sendspace.com/file/pv1571

=====